

Lubrication Maintenance Addendum

2004

**Marquis
Santiam**

The information printed here reflects product design, fabrication, and component parts at the date of printing. The manufacturer reserves the right, at any time, to make changes in product design or material or component specifications as its sole option, without notice. This includes the substitution of components of a different brand or trade name, which will result in comparable performance. All information printed in this document is subject to change after the date of printing. Due to product improvements, changes during the model year and/or transcription errors that may occur, information represented within the owner's manual and/or this document may not be accurate at the time of your purchase. Please confirm any information with your dealer.

The following information supersedes the information published in the 2004 Marquis® Owner's Manual, page 419, section 10 and the 2004 Santiam® Owner's Manual, page 393, section 10. Please utilize the information provided henceforth.

©Monaco Coach Corporation. Beaver®. All rights reserved. All other trademarks or registered trademarks are property of their respective holders. Brand name products of other companies mentioned in this addendum are not endorsed by Monaco Coach Corporation.

ATG04264

The information on page 419 of the Marquis® manual and page 393 of the Santiam® manual should be updated. The updated information (in bold) reflects the following changes:

LUBRICATION MAINTENANCE

The slack adjuster and camshaft need to be lubed periodically to ensure proper brake operation. Lubricate every 10,000 miles or **every six months**.

Current Text:

Rear Drum Brake -

Lubricate until new grease appears at exit points.


Use NCCI #2 Lithium Soap base grease.

Supersedes Current Text:

Rear Drum Brake -

Lubricate until new grease appears at exit points.

Use **NLGI #2** Lithium Soap base grease.



090350c



Monaco Coach Corporation
91320 Coburg Industrial Way
Coburg, OR 97408
800-634-0855
www.beavermotorcoaches.com

Warranty/Technical Support
Toll Free 877-466-6226